

Isle of Man Ship Registry Port State Control Notice

November 2023 PSC Analysis

Ref: 11-2023

Issued: 11 December 2023

1. Introduction

This notice serves to highlight shipowners of recent trends identified following Port State Control Inspections performed across all Manx flagged vessels for November 2023.


The top risk areas identified during this month were:

- Fire Safety
- Pollution Prevention – Ballast Water
- Structural Condition

The Ship Registry advises owners to place particular emphasis on these risk areas during their own inspections to minimise issues during Port State Control. Any concerns/issues following Port State Control should be highlighted to the Ship Registry as soon as possible.

2. PSC Deficiencies – All PSC MoU Regions

The following chart shows deficiency areas requiring corrective action raised in all MoU Regions as a percentage of total deficiencies recorded:



3. PSC Deficiencies by Ship Type – All PSC MoU Regions

The following table shows deficiency items raised by code (Paris MoU coding system) by ship type in all MoU regions.

Vessel Subtype	Bulk Carrier	Commercial Yacht	Gas Carrier	Oil/Chem Tanker	Total
012 - Certificates & Documentation - Crew Certificate		1			1
013 - Certificates & Documentation - Document	1				1
02 - Structural Condition	2				2
04 - Emergency Systems				1	1
07 - Fire Safety	1		3	4	8
10 - Safety of Navigation	1			1	2
13 - Propulsion & Auxiliary Machinery	1				1
146 - Pollution Prevention - MARPOL Annex VI	1				1
148 - Pollution Prevention - Ballast Water				4	4
15 - ISM - Related deficiencies	1			1	2
18 - MLC 2006 - Health Protection, Medical Care, Welfare and Social Security Protection			2		2
Total	8	1	5	11	25

4. PSC Deficiencies – All

The following table shows all deficiencies raised to the IOM Ship Registry due to Port State Control during November 2023.

Deficiency Heading	Deficiency Code	Deficiency Description	Deficiency Comment
012 - Certificates & Documentation - Crew Certificate	1201	Certificates for masters and officers	Master GOC not available during the inspections
013 - Certificates & Documentation - Document	1326	Stability information booklet	Stability book not approved by flag
02 - Structural Condition	2106	Hull damage impairing seaworthiness	Hull damage
	2112	Hull - corrosion	Corrosion of hull
04 - Emergency Systems	4108	Muster list	Muster list not updated
07 - Fire Safety	7103	Division - main zones	Decks, bulkheads and penetrations - not as required
	7105	Fire doors/openings in fire-resisting divisions	Fire doors/openings in fire-resisting divisions Malfunctioning
	7108	Ready availability of fire fighting equipment	Ready availability of fire fighting equipment - missing
	7110	Fire fighting equipment and appliances	Fire fighting equipment and appliances - Not as required
	7114	Means of control (opening/closure skylights, pumps, etc.) - Machinery Spaces	Remote Means of control in Machinery spaces - Inoperative
	7115	Fire-dampers	Fire dampers not as required
	7115	Fire-dampers	Port side engine room ventilation damper seized
	7116	Ventilation	Ventilation - not as required



10 - Safety of Navigation	10103	Radar	Radar found inoperative
	10109	Lights, shapes, sound signals.	Lights, shapes, sound-signals - Inoperative
13 - Propulsion & Auxiliary Machinery	13107	Maintenance procedures for all gas related installations	Lube oil purifier feed pump leaking
146 - Pollution Prevention - MARPOL Annex VI	14608	Incinerator, including operations and operating manual	Incinerator incl. operations and operating manual found Inoperative
148 - Pollution Prevention - Ballast Water	14802	Ballast Water Record Book	Ballast Water Record Book Entries missing
	14806	Crew Training & Familiarisation	Crew Training and familiarization - Lack of familiarity
	14810	Ballast water discharge violation in port	Ballast water discharge violation in port - Not as required
	14811	Ballast Water Management System	Ballast Water Management System malfunctioning
15 - ISM - Related deficiencies	15102	Company responsibility and authority	Near miss records not completed by company
	15150	ISM	ISM internal audit requested within 3 months
18 - MLC 2006 - Health Protection, Medical Care, Welfare and Social Security Protection	18407	Lighting - (Working Spaces)	Damaged working spaces
	18425	Access / Structural features of ship	Access not as required

